Burdick, Melanie[Burdick.Melanie@epa.gov]

From: Wilson, Kristina (DEQ)
Sent: Wed 2/28/2018 3:09:06 PM
Subject: \*deliberative communication\*

To:

8 R-Wetland Permit Application Nov 2017 reduced App B CuttoffWall SlopeStudy Nov2017.pdf

R-Permit Application Back Forty Project CutoffWall SlopeStudy Section Jan2017.pdf

deq-oogm-mining-AquilaBackFortyPermit12282016 546947 7.pdf

Compare: January 2017 document page 11 of 44 with November 2017 document page 10 of 42. Note the location of the existing monitoring wells in comparison to the location of the proposed cutoff wall and pit perimeter.

The permit conditions that have been brought to my attention on the slope stability matter are: K24 and L21.

Kristi Wilson
Department of Environmental Quality
Water Resources Division
Upper Peninsula District Office
1504 W Washington Street
Marquette, MI 49855
906-236-0380